

Equipment Top 10 Cost in Past 365 Days

Rank	Equipment	Equipment Description	Total Cost			
	Work Order	Work Order Description	Material	Services	Labor	Tools
1	11430	Centrifugal Pump 100GPM/60FT HD				9,259
	31150	11430 prob work				
	1488	Condensate Return Pump Leaking	45		186	
	31145	check out problem @ 11430	195		220	22
	6259	Check Low Flow on Condensate Return Pump	495		156	
	5856	Condensate Return Pump Stopped	135		126	
	31140	issue at BR430 - w/11430	185		195	
	4557	Check Condensate Return Pump Pressure Problem	175		76	
	1351	Check Low Flow on Condensate Return Pump	45		176	
	1638	Check Leaking Condensate Return Pump	65		180	
	31135	11430 prob work	185		195	18
	1298	Condensate Return Pump Stopped	45		86	
	1336	fix pump	45		381	
	1277	Repair Leaking Pump	45		356	
	31130	issue at BR430 - w/11430	175		195	
	4233	Pump Stopped			31	
	3838	Check Leaking Condensate Return Pump	129		261	
	1276	Repair Centrifugal Pump	35		61	
	1226	Repair Feed Water Pump	25		61	
	3432	Condensate Return Pump Stopped			68	
	31125	check out problem @ 11430	175		160	12
	3038	Check Leaking Pump	129		183	
	5256	Check Leaking Condensate Return Pump	46		210	
	2861	Condensate Return Pump Flow Stopped	135		183	
	31120	issue at BR430 - w/11430	175		160	
	1311	Pump Failure- Deliver to Shop			453	
	2362	Repair Pump Leak	129		153	
	31115	issue at BR430 - w/11430	175		160	4
	6951	Condensate Return Pump Stopped			56	
	1037	Centrifugal Pump Service - 12 Month				
	1036	Inspect and Repair Relay				
	6727	Condensate Return Pump Leaking	129		166	
	31110	11430 prob work	175		115	
	31105	check out problem @ 11430	175		115	
	1695	Condensate Return Pump Leaking	46		180	
	7721	Condensate Return Pump Leaking	129		53	
	7551	Check Low Flow on Condensate Return Pump	175		35	
		Total	3,819		5,384	56
2	11200	HVAC System- 50 Ton Cool Cap/ 450000 Btu Heat Cap				3,922
	6011	HVAC Quarterly Inspections & Certification	102		381	213
	31250	11200 prob work				
	31245	problem @ 11200	37		160	12

Equipment Top 10 Cost in Past 365 Days

Rank	Equipment	Equipment Description	Total Cost			
	Work Order	Work Order Description	Material	Services	Labor	Tools
	31240	issue at BR200 - w/11200	51		160	
	31740	issue at BR200	25		162	12
	31235	issue at BR200 - see connelly	37		195	18
	31230	issue at BR200 - w/11200	37		160	
	31225	check out problem @ 11200	41		160	12
	31220	issue at BR200 - w/11200	37		160	
	31215	issue at BR200 - see connelly	42		160	4
	31710	issue at BR200	23		210	
	31210	11200 prob work	37		115	
	31705	issue at BR200	23		210	
	31205	problem @ 11200	37		115	
	3001	HVAC Quarterly Inspections & Certification	66		266	72
	5011	HVAC Quarterly Inspections & Certification	67		255	52
		Total	657		2,869	396
3	11450	Centrifugal Pump 100GPM/60FTHD				3,718
	91091	11450 BREAKDOWN	5		76	13
	91071	ANOTHER PROBLEM WITH 11450	5		200	20
	91061	LEAK	225		925	20
	91051	PROBLEM WITH 11450	75		700	20
	90121	11450 STOPPED	22		90	20
	90061	LEAK	22		90	20
	2433	Pump Stopped Running			68	
	89081	11450 PROBLEM	5		76	13
	4394	Pump Stopped			37	
	89041	LEAK	20		51	20
	1002	Rebuild Feedwater Pump				
	1006	Feedwater Pump Service	141			
	87091	11450 PROBLEM	55		161	33
	2155	Pump Leaking			19	
	88051	11450 PROBLEM	55		161	33
	88111	LEAK	40		126	20
	7492	Pump Stopped			37	
		Total	670		2,815	233
4	11300	Reciprocating Compressor- Air Cooled/100 CFM				3,275
	6012	Compressor Quarterly Inspection and Certification	105		566	119
	31755	11300 prob work-see miller	25			
	31750	see miller - 11300 prob work	35		162	25
	31745	problem @ 11300	25		122	12
	31735	SEE MILLER FOR DETAILS	25		320	15
	31730	issue at BR300	44		165	5
	31725	SEE MILLER FOR DETAILS	23		120	13
	31720	issue at BR300	33		110	

Equipment Top 10 Cost in Past 365 Days

Rank	Equipment	Equipment Description	Total Cost			
	Work Order	Work Order Description	Material	Services	Labor	Tools
	31715	issue at BR300	23		240	8
	1000	Relocate Guard Rails Around Compressor				
	3002	Compressor Quarterly Inspection and Certification	38		296	87
	5012	Compressor Quarterly Inspection and Certification	46		275	67
	7331	Engineering and layout drawings			128	
		Total	420		2,504	351
5	13140	Conveyor System- Pkg. Dept.				3,156
	31655	13140 prob work-check w/connelly on details	38			
	31650	see connelly - 13140 prob work	38		152	25
	30066	problem at 13140	25		185	
	31645	problem @ 13140	38		102	12
	30034	PROBLEM	25		185	6
	31640	problem @ 13140	38		152	12
	30023	Problem with 13110	25		98	
	31635	SEE CONNELLY	35		300	15
	30002	CHECK OUT JAM	25		116	4
	31630	issue w/13140	35		150	5
	31625	issue w/13140	35		100	13
	29877	CHECK OUT JAM	25		236	41
	31620	see connelly - 13140 prob work	35		150	
	31610	SEE CONNELLY	35		190	
	29862	CHECK OUT JAM	25		116	4
	31605	issue w/13140	35		190	
	1019	Conveyor Overhaul- Pkg. Dept.	4		74	12
		Total	514		2,494	148
6	13110	Feeder System				2,703
	61011	PROBLEM	21		300	125
	6004	Feeder Jammed			244	
	61010	PROBLEM	6		175	55
	30157	13110 problem				
	30035	13110 - CHECK OUT JAM	26		135	
	61009	PROBLEM @ BPM3100	21		300	125
	61008	PROBLEM W 13110 -SEE CONNELLY	21		175	125
	61004	PROBLEM @ BPM3100	6		300	55
	29861	CHECK OUT JAM	25		116	4
	2004	Feeder Jammed				
	5004	Feeder Jammed				
	3007	Feeder System Inspection and Certification	37		255	52
		Total	160		1,999	543
7	12600	Conveyor System #1				2,699
	1001	12 Month Service on Shipping Dept #1 Conveyor			2,699	

Equipment Top 10 Cost in Past 365 Days

Rank	Equipment Work Order	Equipment Description Work Order Description	Total Cost			
			Material	Services	Labor	Tools
			Total	2,699		
8	B12600	Pneumatic Sealer				2,671
	B31723	PROBLEM	17		130	8
	B31803	PROBLEM	16		195	33
	B31717	PROBLEM	10		125	32
	B31808	SEE SUP	22		180	10
	B31707	PROB	17		210	12
	B31725	PROB AT MA	15		180	32
	B21805	MECH ASSY	22		180	11
	B21706	MECH ASSY	13		180	13
	B21723	PROBLEM	9		196	9
	B21201	DIFFICULTY STARTING	24		120	13
	B21808	SEE SUP	22		172	10
	B12807	PROB	13		130	89
	B21793	NEED HELP	20		170	13
			Total	220	2,168	283
9	13170	Top Sealer System				2,651
	30058	13170 problem	135			
	30067	problem at 13170	135		185	
	30037	13170 - CHECK OUT JAM	135		135	
	30048	PROBLEM	135		185	15
	30029	problem at 13170	129		98	129
	30007	something up with 13170	129		236	129
	29879	leakage	129		236	129
	29864	something up with 13170	129		116	4
			Total	1,056	1,189	406
10	12710	30 Hp Drive Motor- Conveyor System #2				2,211
	31555	12710 prob work-check w/boyd on details	25			
	31550	see boyd - 12710 prob work	35		162	25
	31545	problem @ 12710	25		122	12
	31540	issue at SHIPPING - w/12710	25		162	12
	31535	SHIPPING - SEE BOYD	25		320	15
	31530	issue at shipping - w/12710	44		165	5
	31525	issue at SHIPPING - w/12710	23		120	13
	31520	issue - w/12710	33		110	
	31515	SHIPPING - SEE BOYD	23		240	8
	31510	issue - w/12710	23		210	
	31505	issue at SHIPPING - w/12710	23		210	
			Total	301	1,821	89