

Equipment Top 10 Time in Past 365 Days

Rank	Equipment Work Order	Equipment Description Work Order Description	Hours Hours
1	11430	Centrifugal Pump 100GPM/60FT HD	91
	31150	11430 prob work	
	1488	Condensate Return Pump Leaking	3
	31145	check out problem @ 11430	4
	6259	Check Low Flow on Condensate Return Pump	3
	5856	Condensate Return Pump Stopped	2
	31140	issue at BR430 - w/11430	4
	4557	Check Condensate Return Pump Pressure Problem	1
	1351	Check Low Flow on Condensate Return Pump	3
	1638	Check Leaking Condensate Return Pump	2
	31135	11430 prob work	4
	1298	Condensate Return Pump Stopped	1
	1336	fix pump	8
	1277	Repair Leaking Pump	4
	31130	issue at BR430 - w/11430	4
	4233	Pump Stopped	1
	3838	Check Leaking Condensate Return Pump	4
	1276	Repair Centrifugal Pump	2
	1226	Repair Feed Water Pump	2
	3432	Condensate Return Pump Stopped	1
	31125	check out problem @ 11430	3
	3038	Check Leaking Pump	3
	5256	Check Leaking Condensate Return Pump	2
	2861	Condensate Return Pump Flow Stopped	3
	31120	issue at BR430 - w/11430	3
	1311	Pump Failure- Deliver to Shop	7
	2362	Repair Pump Leak	2
	31115	issue at BR430 - w/11430	3
	6951	Condensate Return Pump Stopped	1
	1037	Centrifugal Pump Service - 12 Month	
	1036	Inspect and Repair Relay	
	6727	Condensate Return Pump Leaking	3
	31110	11430 prob work	3
	31105	check out problem @ 11430	3
	1695	Condensate Return Pump Leaking	2
	7721	Condensate Return Pump Leaking	3
	7551	Check Low Flow on Condensate Return Pump	2
2	11200	HVAC System- 50 Ton Cool Cap/ 450000 Btu Heat Cap	74
	6011	HVAC Quarterly Inspections & Certification	18
	31250	11200 prob work	
	31245	problem @ 11200	3
	31240	issue at BR200 - w/11200	3
	31740	issue at BR200	2

Equipment Top 10 Time in Past 365 Days

Rank	Equipment Work Order	Equipment Description Work Order Description	Hours Hours
	31235	issue at BR200 - see connelly	4
	31230	issue at BR200 - w/11200	3
	31225	check out problem @ 11200	3
	31220	issue at BR200 - w/11200	3
	31215	issue at BR200 - see connelly	3
	31710	issue at BR200	3
	31210	11200 prob work	3
	31705	issue at BR200	3
	31205	problem @ 11200	3
	3001	HVAC Quarterly Inspections & Certification	11
	5011	HVAC Quarterly Inspections & Certification	12
3	11300	Reciprocating Compressor- Air Cooled/100 CFM	72
	6012	Compressor Quarterly Inspection and Certification	29
	31755	11300 prob work-see miller	
	31750	see miller - 11300 prob work	2
	31745	problem @ 11300	2
	31735	SEE MILLER FOR DETAILS	4
	31730	issue at BR300	2
	31725	SEE MILLER FOR DETAILS	2
	31720	issue at BR300	2
	31715	issue at BR300	3
	1000	Relocate Guard Rails Around Compressor	
	3002	Compressor Quarterly Inspection and Certification	12
	5012	Compressor Quarterly Inspection and Certification	11
	7331	Engineering and layout drawings	4
4	11450	Centrifugal Pump 100GPM/60FTHD	58
	91091	11450 BREAKDOWN	3
	91071	ANOTHER PROBLEM WITH 11450	4
	91061	LEAK	15
	91051	PROBLEM WITH 11450	10
	90121	11450 STOPPED	2
	90061	LEAK	2
	2433	Pump Stopped Running	1
	89081	11450 PROBLEM	3
	4394	Pump Stopped	2
	89041	LEAK	2
	1002	Rebuild Feedwater Pump	
	1006	Feedwater Pump Service	
	87091	11450 PROBLEM	4
	2155	Pump Leaking	1
	88051	11450 PROBLEM	4
	88111	LEAK	4
	7492	Pump Stopped	2

Equipment Top 10 Time in Past 365 Days

Rank	Equipment Work Order	Equipment Description Work Order Description	Hours Hours
5	11460	Burner, Gas Fired- For Boiler	53
	6013	Burner Quarterly Inspection and Certification	29
	2392	Burner Flame Problem	1
	3003	Burner Quarterly Inspection and Certification	11
	5013	Burner Quarterly Inspection and Certification	11
	7291	No Flame in Boiler Burner	1
6	12100	Forklift #1	44
	6015	Forklift #1 Quarterly Inspection and Certification	21
	3005	Forklift #1 Quarterly Inspection and Certification	12
	5015	Forklift #1 Quarterly Inspection and Certification	11
7	13140	Conveyor System- Pkg. Dept.	42
	31655	13140 prob work-check w/connelly on details	
	31650	see connelly - 13140 prob work	2
	30066	problem at 13140	4
	31645	problem @ 13140	2
	30034	PROBLEM	4
	31640	problem @ 13140	2
	30023	Problem with 13110	2
	31635	SEE CONNELLY	4
	30002	CHECK OUT JAM	2
	31630	issue w/13140	2
	31625	issue w/13140	2
	29877	CHECK OUT JAM	4
	31620	see connelly - 13140 prob work	2
	31610	SEE CONNELLY	3
	29862	CHECK OUT JAM	3
	31605	issue w/13140	3
	1019	Conveyor Overhaul- Pkg. Dept.	4
8	12210	Brake System- Overhead Crane #1	41
	6014	Crane Quarterly Inspection and Certification	18
	3004	Crane Quarterly Inspection and Certification	11
	5014	Crane Quarterly Inspection and Certification	12
9	12700	Conveyor System #2	33
	6010	12 Month Service on Shipping Dept #2 Conveyor	21
	5010	12 Month Service on Shipping Dept #2 Conveyor	12
10	13110	Feeder System	33
	61011	PROBLEM	4
	6004	Feeder Jammed	
	61010	PROBLEM	2
	30157	13110 problem	
	30035	13110 - CHECK OUT JAM	3
	61009	PROBLEM @ BPM3100	4
	61008	PROBLEM W 13110 -SEE CONNELLY	2

Equipment Top 10 Time in Past 365 Days

Rank	Equipment Work Order	Equipment Description Work Order Description	Hours Hours
	61004	PROBLEM @ BPM3100	4
	29861	CHECK OUT JAM	3
	2004	Feeder Jammed	
	5004	Feeder Jammed	
	3007	Feeder System Inspection and Certification	12