

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Status | Priority |
|-----------|---|------------|--|----------|---------------|----------|
| 1001 | Fire Extinguisher | | | MOFLOOR | | 3 |
| 1002 | Fire Extinguisher | | | MOFLOOR | | 3 |
| 1003 | Fire Extinguisher | | | MOFLOOR | | 3 |
| 1004 | Fire Extinguisher | | | MOFLOOR | | 3 |
| 1005 | Fire Extinguisher | | | CONF400 | | 3 |
| 1006 | Fire Extinguisher | | | OFF401 | | 3 |
| 1007 | Fire Extinguisher | | | OFF402 | | 3 |
| 11200 | HVAC System- 50 Ton Cool Cap/ 450000 Btu Heat Cap | | | BR200 | | 4 |
| | | WO: 6011 | HVAC Quarterly Inspections & Certification | | Status: CLOSE | |
| | | WO: 31250 | 11200 prob work | | Status: APPR | |
| | | WO: 31245 | problem @ 11200 | | Status: CLOSE | |
| | | WO: 31240 | issue at BR200 - w/11200 | | Status: CLOSE | |
| | | WO: 31740 | issue at BR200 | | Status: CLOSE | |
| | | WO: 31235 | issue at BR200 - see connelly | | Status: CLOSE | |
| | | WO: 31230 | issue at BR200 - w/11200 | | Status: CLOSE | |
| | | WO: 31225 | check out problem @ 11200 | | Status: CLOSE | |
| | | WO: 31220 | issue at BR200 - w/11200 | | Status: CLOSE | |
| | | WO: 31215 | issue at BR200 - see connelly | | Status: CLOSE | |
| | | WO: 31710 | issue at BR200 | | Status: CLOSE | |
| | | WO: 31210 | 11200 prob work | | Status: CLOSE | |
| | | WO: 31705 | issue at BR200 | | Status: CLOSE | |
| | | WO: 31205 | problem @ 11200 | | Status: CLOSE | |
| | | WO: 3001 | HVAC Quarterly Inspections & Certification | | Status: CLOSE | |
| | | WO: 5011 | HVAC Quarterly Inspections & Certification | | Status: CLOSE | |
| 11210 | Circulation Fan- Centrifugal/ 20/000 CFM | | | BR210 | | 5 |
| | | WO: 1018 | Paint Guard Rail Around #1 Fan | | Status: WAPPR | |
| | 11211 Motor Starter- Size 2/440v/3ph/60cy | | | BR210 | | 3 |
| 11240 | Circulation Fan- Centrifugal/ 20/000 CFM | | | BR240 | | 5 |
| 11250 | Circulation Fan- Centrifugal/ 20/000 CFM | | | BR200 | | 5 |
| 11220 | Electrical Control Panel- HVAC System | | | ECC210 | | 4 |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|--|------------|---|----------|---------------|
| | | | | Status | |
| 11230 | Emergency Generator | | | BR230 | 5 |
| | | WO: 1020 | Generator Overhaul | | Status: WSCH |
| | | WO: 1004 | Generator Overhaul | | Status: INPRG |
| | | WO: 1008 | Repair Damaged Conduit Feeding Generator | | Status: WAPPR |
| 11300 | Reciprocating Compressor- Air Cooled/100 CFM | | | BR300 | 5 |
| | | WO: 6012 | Compressor Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 31755 | 11300 prob work-see miller | | Status: APPR |
| | | WO: 31750 | see miller - 11300 prob work | | Status: CLOSE |
| | | WO: 31745 | problem @ 11300 | | Status: CLOSE |
| | | WO: 31735 | SEE MILLER FOR DETAILS | | Status: CLOSE |
| | | WO: 31730 | issue at BR300 | | Status: CLOSE |
| | | WO: 31725 | SEE MILLER FOR DETAILS | | Status: CLOSE |
| | | WO: 31720 | issue at BR300 | | Status: CLOSE |
| | | WO: 31715 | issue at BR300 | | Status: CLOSE |
| | | WO: 1000 | Relocate Guard Rails Around Compressor | | Status: WAPPR |
| | | WO: 3002 | Compressor Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 5012 | Compressor Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 7331 | Engineering and layout drawings | | Status: WAPPR |
| 11340 | Motor Starter- Size 4/NEMA 12/440v/3ph/60hz | | | BR300 | 4 |
| 11400 | Boiler- 50,000 Lb/Hr/ Gas Fired/ Water Tube | | | BR400 | 5 |
| | | WO: 4922 | Boiler Stopped | | Status: CLOSE |
| | | WO: 1254 | Boiler Stopped | | Status: CLOSE |
| | | WO: 2954 | Boiler Stopped | | Status: CLOSE |
| | | WO: 7244 | Boiler Stopped | | Status: CLOSE |
| 11430 | Centrifugal Pump 100GPM/60FT HD | | | BR430 | |
| | | WO: 31150 | 11430 prob work | | Status: APPR |
| | | WO: 1488 | Condensate Return Pump Leaking | | Status: CLOSE |
| | | WO: 31145 | check out problem @ 11430 | | Status: CLOSE |
| | | WO: 6259 | Check Low Flow on Condensate Return Pump | | Status: CLOSE |
| | | WO: 5856 | Condensate Return Pump Stopped | | Status: CLOSE |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|-------------|------------|---|----------|---------------|
| | | | | Status | |
| | | WO: 31140 | issue at BR430 - w/11430 | | Status: CLOSE |
| | | WO: 4557 | Check Condensate Return Pump Pressure Problem | | Status: CLOSE |
| | | WO: 1351 | Check Low Flow on Condensate Return Pump | | Status: CLOSE |
| | | WO: 1638 | Check Leaking Condensate Return Pump | | Status: CLOSE |
| | | WO: 31135 | 11430 prob work | | Status: CLOSE |
| | | WO: 1298 | Condensate Return Pump Stopped | | Status: CLOSE |
| | | WO: 1336 | fix pump | | Status: CLOSE |
| | | WO: 1277 | Repair Leaking Pump | | Status: CLOSE |
| | | WO: 31130 | issue at BR430 - w/11430 | | Status: CLOSE |
| | | WO: 4233 | Pump Stopped | | Status: CLOSE |
| | | WO: 3838 | Check Leaking Condensate Return Pump | | Status: CLOSE |
| | | WO: 1276 | Repair Centrifugal Pump | | Status: CLOSE |
| | | WO: 1226 | Repair Feed Water Pump | | Status: CLOSE |
| | | WO: 3432 | Condensate Return Pump Stopped | | Status: CLOSE |
| | | WO: 31125 | check out problem @ 11430 | | Status: CLOSE |
| | | WO: 3038 | Check Leaking Pump | | Status: CLOSE |
| | | WO: 5256 | Check Leaking Condensate Return Pump | | Status: CLOSE |
| | | WO: 2861 | Condensate Return Pump Flow Stopped | | Status: CLOSE |
| | | WO: 31120 | issue at BR430 - w/11430 | | Status: CLOSE |
| | | WO: 1311 | Pump Failure- Deliver to Shop | | Status: CLOSE |
| | | WO: 2362 | Repair Pump Leak | | Status: CLOSE |
| | | WO: 31115 | issue at BR430 - w/11430 | | Status: CLOSE |
| | | WO: 6951 | Condensate Return Pump Stopped | | Status: CLOSE |
| | | WO: 1037 | Centrifugal Pump Service - 12 Month | | Status: CLOSE |
| | | WO: 1036 | Inspect and Repair Relay | | Status: CLOSE |
| | | WO: 6727 | Condensate Return Pump Leaking | | Status: CLOSE |
| | | WO: 31110 | 11430 prob work | | Status: CLOSE |
| | | WO: 31105 | check out problem @ 11430 | | Status: CLOSE |
| | | WO: 1695 | Condensate Return Pump Leaking | | Status: CLOSE |
| | | WO: 7721 | Condensate Return Pump Leaking | | Status: CLOSE |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|---|------------|---|----------|---------------|
| | | | | Status | |
| | | WO: 7551 | Check Low Flow on Condensate Return Pump | | Status: CLOSE |
| 23972 | Motor- 10hp/1750rpm/TEFC/254T Frame/440v/3ph/60hz | | | BR431 | 3 |
| 11450 | Centrifugal Pump 100GPM/60FTHD | | | BR450 | |
| | | WO: 91091 | 11450 BREAKDOWN | | Status: APPR |
| | | WO: 91071 | ANOTHER PROBLEM WITH 11450 | | Status: CLOSE |
| | | WO: 91061 | LEAK | | Status: CLOSE |
| | | WO: 91051 | PROBLEM WITH 11450 | | Status: CLOSE |
| | | WO: 90121 | 11450 STOPPED | | Status: CLOSE |
| | | WO: 90061 | LEAK | | Status: CLOSE |
| | | WO: 2433 | Pump Stopped Running | | Status: CLOSE |
| | | WO: 89081 | 11450 PROBLEM | | Status: CLOSE |
| | | WO: 4394 | Pump Stopped | | Status: CLOSE |
| | | WO: 89041 | LEAK | | Status: CLOSE |
| | | WO: 1002 | Rebuild Feedwater Pump | | Status: APPR |
| | | WO: 1006 | Feedwater Pump Service | | Status: APPR |
| | | WO: 87091 | 11450 PROBLEM | | Status: CLOSE |
| | | WO: 2155 | Pump Leaking | | Status: CLOSE |
| | | WO: 88051 | 11450 PROBLEM | | Status: CLOSE |
| | | WO: 88111 | LEAK | | Status: CLOSE |
| | | WO: 7492 | Pump Stopped | | Status: CLOSE |
| 49332 | Motor- 10hp/1750rpm/TEFC/254T Frame/440v/3ph/60hz | | | BR451 | 4 |
| 11460 | Burner, Gas Fired- For Boiler | | | BR460 | 5 |
| | | WO: 6013 | Burner Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 2392 | Burner Flame Problem | | Status: CLOSE |
| | | WO: 3003 | Burner Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 5013 | Burner Quarterly Inspection and Certification | | Status: CLOSE |
| | | WO: 7291 | No Flame in Boiler Burner | | Status: CLOSE |
| 11470 | Centrifugal Pump 100 GPM, 60 FT-HD | | | REPAIR | |
| | | WO: 1013 | Inspect and Repair Pump as Required | | Status: APPR |
| 11480 | Centrifugal Pump 100 GPM, 60 FT-HD | | | CENTRAL | |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|---------------------------------------|------------|--|---------------|----------|
| | | | | Status | |
| 12100 | Forklift #1 | | | SHIPPING | 3 |
| | | WO: 6015 | Forklift #1 Quarterly Inspection and Certification | Status: CLOSE | |
| | | WO: 3005 | Forklift #1 Quarterly Inspection and Certification | Status: CLOSE | |
| | | WO: 5015 | Forklift #1 Quarterly Inspection and Certification | Status: CLOSE | |
| 12200 | Overhead Crane #1 | | | SHIPPING | 4 |
| 12210 | Brake System- Overhead Crane #1 | | | SHIPPING | 5 |
| | | WO: 6014 | Crane Quarterly Inspection and Certification | Status: CLOSE | |
| | | WO: 3004 | Crane Quarterly Inspection and Certification | Status: CLOSE | |
| | | WO: 5014 | Crane Quarterly Inspection and Certification | Status: CLOSE | |
| 12222 | Centrifugal Pump 100 GPM, 60 FT-HD | | | CENTRAL | |
| 12300 | Electric Cart | | | SHIPPING | 2 |
| | | WO: 1005 | Electric Cart Tune-Up | Status: APPR | |
| 12400 | Forklift #2 | | | SHIPPING | 4 |
| | | WO: 3010 | Forklift #2 Quarterly Inspection and Certification | Status: CLOSE | |
| 12500 | Overhead Crane #2 | | | SHIPPING | 5 |
| 12510 | Brake System- Overhead Crane #2 | | | SHIPPING | 5 |
| 12600 | Conveyor System #1 | | | SHIPPING | 4 |
| | | WO: 1001 | 12 Month Service on Shipping Dept #1 Conveyor | Status: INPRG | |
| 12610 | 30 Hp Drive Motor- Conveyor System #1 | | | SHIPPING | 3 |
| | | WO: 31450 | see boyd - 12610 prob work | Status: APPR | |
| | | WO: 31445 | problem @ 12610 | Status: CLOSE | |
| | | WO: 31440 | issue at SHIPPING - w/12610 | Status: CLOSE | |
| | | WO: 31435 | SHIPPING - SEE BOYD | Status: CLOSE | |
| | | WO: 31430 | issue at shipping - w/12610 | Status: CLOSE | |
| | | WO: 31425 | issue at SHIPPING - w/12610 | Status: CLOSE | |
| | | WO: 31420 | issue - w/12610 | Status: CLOSE | |
| | | WO: 31415 | SHIPPING - SEE BOYD | Status: CLOSE | |
| | | WO: 31410 | issue - w/12610 | Status: CLOSE | |
| | | WO: 31405 | issue at SHIPPING - w/12610 | Status: CLOSE | |
| 12700 | Conveyor System #2 | | | SHIPPING | 4 |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority | |
|-----------|---------------------------------------|------------|---|----------|---------------|---------|
| | | | | Status | | |
| 12710 | 30 Hp Drive Motor- Conveyor System #2 | WO: 6010 | 12 Month Service on Shipping Dept #2 Conveyor | | Status: CLOSE | |
| | | WO: 5010 | 12 Month Service on Shipping Dept #2 Conveyor | | Status: CLOSE | |
| | | | | SHIPPING | 3 | |
| | | WO: 31555 | 12710 prob work-check w/boyd on details | | Status: APPR | |
| | | WO: 31550 | see boyd - 12710 prob work | | Status: CLOSE | |
| | | WO: 31545 | problem @ 12710 | | Status: CLOSE | |
| | | WO: 31540 | issue at SHIPPING - w/12710 | | Status: CLOSE | |
| | | WO: 31535 | SHIPPING - SEE BOYD | | Status: CLOSE | |
| | | WO: 31530 | issue at shipping - w/12710 | | Status: CLOSE | |
| | | WO: 31525 | issue at SHIPPING - w/12710 | | Status: CLOSE | |
| | | WO: 31520 | issue - w/12710 | | Status: CLOSE | |
| | | WO: 31515 | SHIPPING - SEE BOYD | | Status: CLOSE | |
| | | WO: 31510 | issue - w/12710 | | Status: CLOSE | |
| | | WO: 31505 | issue at SHIPPING - w/12710 | | Status: CLOSE | |
| 13110 | Feeder System | | | BPM3100 | 3 | |
| | | WO: 61011 | PROBLEM | | Status: CLOSE | |
| | | WO: 6004 | Feeder Jammed | | Status: WAPPR | |
| | | WO: 61010 | PROBLEM | | Status: CLOSE | |
| | | WO: 30157 | 13110 problem | | Status: APPR | |
| | | WO: 30035 | 13110 - CHECK OUT JAM | | Status: CLOSE | |
| | | WO: 61009 | PROBLEM @ BPM3100 | | Status: CLOSE | |
| | | WO: 61008 | PROBLEM W 13110 -SEE CONNELLY | | Status: CLOSE | |
| | | WO: 61004 | PROBLEM @ BPM3100 | | Status: CLOSE | |
| | | WO: 29861 | CHECK OUT JAM | | Status: CLOSE | |
| | | WO: 2004 | Feeder Jammed | | Status: INPRG | |
| | | WO: 5004 | Feeder Jammed | | Status: WAPPR | |
| | | WO: 3007 | Feeder System Inspection and Certification | | Status: CLOSE | |
| | | 13120 | Bottom Sealing System | | | BPM3100 |
| WO: 30056 | 13120 problem | | | | Status: APPR | |
| WO: 30065 | problem at 13120 | | | | Status: APPR | |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|--------------------------------------|------------|--|----------|---------------|
| | | | | Status | |
| | | WO: 36034 | 13120 - CHECK OUT ISSUE | | Status: CLOSE |
| | | WO: 30043 | PROBLEM | | Status: CLOSE |
| | | WO: 30022 | Problem with 13120 | | Status: CLOSE |
| | | WO: 30001 | Per Connelly, prob at 13120 | | Status: CLOSE |
| | | WO: 3009 | Bottom Sealing System Inspection and Certification | | Status: CLOSE |
| 13130 | Stripper System | | | BPM3100 | 3 |
| 13140 | Conveyor System- Pkg. Dept. | | | BPM3100 | 4 |
| | | WO: 31655 | 13140 prob work-check w/connelly on details | | Status: APPR |
| | | WO: 31650 | see connelly - 13140 prob work | | Status: CLOSE |
| | | WO: 30066 | problem at 13140 | | Status: APPR |
| | | WO: 31645 | problem @ 13140 | | Status: CLOSE |
| | | WO: 30034 | PROBLEM | | Status: CLOSE |
| | | WO: 31640 | problem @ 13140 | | Status: CLOSE |
| | | WO: 30023 | Problem with 13110 | | Status: CLOSE |
| | | WO: 31635 | SEE CONNELLY | | Status: CLOSE |
| | | WO: 30002 | CHECK OUT JAM | | Status: CLOSE |
| | | WO: 31630 | issue w/13140 | | Status: CLOSE |
| | | WO: 31625 | issue w/13140 | | Status: CLOSE |
| | | WO: 29877 | CHECK OUT JAM | | Status: CLOSE |
| | | WO: 31620 | see connelly - 13140 prob work | | Status: CLOSE |
| | | WO: 31610 | SEE CONNELLY | | Status: CLOSE |
| | | WO: 29862 | CHECK OUT JAM | | Status: CLOSE |
| | | WO: 31605 | issue w/13140 | | Status: CLOSE |
| | | WO: 1019 | Conveyor Overhaul- Pkg. Dept. | | Status: COMP |
| 13141 | Elevator Rails And Drainpan Assembly | | | BPM3100 | 2 |
| | | WO: 1007 | Packaging Mach. Elevator & Drainpan Inspection | | Status: APPR |
| | | WO: 3011 | PKG Dept. Elevator Inspections & Certification | | Status: CLOSE |
| 13142 | Carton Escapement Assembly #2 | | | BPM3100 | 3 |
| 13143 | Chain Wash Assembly | | | BPM3100 | 4 |
| | | WO: 6006 | Check-out Alignment of Steel Support Bracket | | Status: WAPPR |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|-------------------------------|------------|--|----------|---------------|
| | | | | Status | |
| | | WO: 2006 | Check-out Alignment of Steel Support Bracket | | Status: WAPPR |
| | | WO: 5006 | Check-out Alignment of Steel Support Bracket | | Status: WAPPR |
| 13144 | Carton Escapement Assembly #1 | | | BPM3100 | 3 |
| 13145 | Indexing Drive Assembly | | | BPM3100 | 3 |
| | | WO: 6005 | Check-out Leaking | | Status: WAPPR |
| | | WO: 2005 | Check-out Leaking | | Status: WAPPR |
| | | WO: 5005 | Check-out Leaking | | Status: WAPPR |
| 13150 | Top Breaker System | | | BPM3100 | 3 |
| | | WO: 3006 | Top Breaker Quarterly Inspection and Certification | | Status: CLOSE |
| 13160 | Filler And Lifter System | | | BPM3100 | 2 |
| | | WO: 3008 | Filler/Lifter System Inspection and Certification | | Status: CLOSE |
| 13170 | Top Sealer System | | | BPM3100 | 2 |
| | | WO: 30058 | 13170 problem | | Status: APPR |
| | | WO: 30067 | problem at 13170 | | Status: APPR |
| | | WO: 30037 | 13170 - CHECK OUT JAM | | Status: CLOSE |
| | | WO: 30048 | PROBLEM | | Status: CLOSE |
| | | WO: 30029 | problem at 13170 | | Status: CLOSE |
| | | WO: 30007 | something up with 13170 | | Status: CLOSE |
| | | WO: 29879 | leakage | | Status: CLOSE |
| | | WO: 29864 | something up with 13170 | | Status: CLOSE |
| 13180 | Lubrication System | | | BPM3100 | 3 |
| | | WO: 31350 | see connelly - 13180 prob work | | Status: APPR |
| | | WO: 31345 | problem @ 13180 | | Status: CLOSE |
| | | WO: 31340 | issue at BPM3100 - w/13180 | | Status: CLOSE |
| | | WO: 31335 | issue at BPM3100 - see connelly | | Status: CLOSE |
| | | WO: 31330 | issue at BPM3100 - w/13180 | | Status: CLOSE |
| | | WO: 31325 | check out problem @ 13180 | | Status: CLOSE |
| | | WO: 31320 | issue at BPM3100 - w/13180 | | Status: CLOSE |
| | | WO: 31315 | see connelly on 13180 | | Status: CLOSE |
| | | WO: 31310 | check out problem @ 13180 | | Status: CLOSE |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|---|------------|---|----------|---------------|
| | | | | Status | |
| | | WO: 31305 | issue at BPM3100 - w/13180 | | Status: CLOSE |
| 26000 | Motor Controlled Valve | | | MTP100 | 5 |
| 26020 | 24 Volt-DC Motor | | | MTP100 | 5 |
| 26200 | Motor Controlled Valve | | | | 5 |
| 52300 | Electrical Service Pole #300/Wood/45 ft/Class 5 | | | POLE300 | 5 |
| | | WO: 1043 | Remove old pole | | Status: WAPPR |
| | | WO: 1042 | Transfer cables from old pole to new pole | | Status: WAPPR |
| | | WO: 1041 | Install new pole | | Status: WAPPR |
| | | WO: 1040 | Dig hole for new service pole | | Status: WAPPR |
| 61001 | Freightliner #61001 | | | EAST | |
| 61002 | Freightliner #61002 | | | EAST | |
| 61003 | Freightliner #61003 | | | EAST | |
| 61004 | Freightliner #61004 | | | EAST | |
| B12210 | pellet blower | | | FINALPKG | 5 |
| B12510 | stamping machine | | | MARKING | 3 |
| | | WO: B33803 | PROBLEM | | Status: CLOSE |
| | | WO: B33717 | PROBLEM | | Status: CLOSE |
| | | WO: B22706 | MECH ASSY | | Status: CLOSE |
| | | WO: B22717 | PROBLEM | | Status: CLOSE |
| | | WO: B22793 | NEED HELP | | Status: CLOSE |
| B12540 | STAMPING MACH | | | | 2 |
| B12550 | stamping machine | | | MARKING | 3 |
| | | WO: B33723 | PROBLEM | | Status: CLOSE |
| | | WO: B33808 | SEE SUP | | Status: CLOSE |
| | | WO: B33707 | PROB | | Status: CLOSE |
| | | WO: B33725 | PROB AT MA | | Status: CLOSE |
| | | WO: B22725 | PROB AT MA | | Status: CLOSE |
| | | WO: B22803 | PROBLEM | | Status: CLOSE |
| | | WO: B22808 | SEE SUP | | Status: CLOSE |
| B12560 | marking machine | | | | 2 |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Status | Priority |
|-----------|-------------------------------------|------------|---------------------|----------|---------------|----------|
| B12570 | stamoing machine | | | MARKING | | 2 |
| B12600 | Pneumatic Sealer | | | FINALPKG | | 3 |
| | | WO: B31723 | PROBLEM | | Status: CLOSE | |
| | | WO: B31803 | PROBLEM | | Status: CLOSE | |
| | | WO: B31717 | PROBLEM | | Status: CLOSE | |
| | | WO: B31808 | SEE SUP | | Status: CLOSE | |
| | | WO: B31707 | PROB | | Status: CLOSE | |
| | | WO: B31725 | PROB AT MA | | Status: CLOSE | |
| | | WO: B21805 | MECH ASSY | | Status: CLOSE | |
| | | WO: B21706 | MECH ASSY | | Status: CLOSE | |
| | | WO: B21723 | PROBLEM | | Status: CLOSE | |
| | | WO: B21201 | DIFFICULTY STARTING | | Status: CLOSE | |
| | | WO: B21808 | SEE SUP | | Status: CLOSE | |
| | | WO: B12807 | PROB | | Status: CLOSE | |
| | | WO: B21793 | NEED HELP | | Status: CLOSE | |
| B12700 | Pneumatic Sealer | | | FINALPKG | | 3 |
| | | WO: B31805 | MECH ASSY | | Status: CLOSE | |
| | | WO: B31201 | DIFFICULTY STARTING | | Status: CLOSE | |
| | | WO: B31807 | PROB | | Status: CLOSE | |
| | | WO: B31793 | NEED HELP | | Status: CLOSE | |
| | | WO: B31706 | MECH ASSY | | Status: CLOSE | |
| | | WO: B21707 | PROB | | Status: CLOSE | |
| | | WO: B21725 | PROB AT MA | | Status: CLOSE | |
| | | WO: B21803 | PROBLEM | | Status: CLOSE | |
| | | WO: B21717 | PROBLEM | | Status: CLOSE | |
| DISPL1 | DataStar ViewAll Display Monitor | | | CONF100 | | |
| MH#1660 | Manhole Assembly Unit #1660 | | | MH100 | | 0 |
| CONE-001 | Waste Catch Cone - Unit #001 | | | MH100 | | 0 |
| COVER-01 | Manhole Cover Unit #01 | | | MH100 | | 0 |
| GRT-001 | Manhole Grating Structure Unit #001 | | | MH100 | | 0 |

Equipment and Work Orders

in last 365 days

| Equipment | Description | Work Order | Description | Location | Priority |
|-----------|-------------------------|------------|------------------------|----------|----------|
| | | | | Status | |
| OVHD1 | Overhead Projector | | | CONF100 | |
| | LCD1 | | LCD Panel for Overhead | CONF100 | |
| PC1001 | DataStar Desk Wizard PC | | | PC-CONF1 | |
| PC1002 | DataStar Desk Wizard PC | | | PC-CONF2 | |